



Factory name	Tai Yang Enterprise Co., Ltd.
Address	National Road #4, Bekchan Commune, Angsnuol District, Kandal Province
Total Number of Workers	1938 (278 males)
Date of Last Assessment	6-May-15
No. of Assessments	16
Date of Establishment	May-98
Factory Owner	Taiwanese
Purpose	Spot Check
Requested by	CSR Assistant Manager
Source of Information	Documents, Management, Workers
Date of Visit	23-Sep-15
Date of Report	25-Sep-15

Non Compliance Issues		Assessment Report	Spot Check report	
No.	Output	Summaries of BFC findings*	Compliance	Compliance
1	Dangerous machine parts have safety guards (not needle guards)	During the workplace observation, we noted that approximately 90-95% of the sewing machines had proper needle guards and belt covers. However, we found that 3 washing machines did not have belt covers and that machines were not regularly maintained.	x	Based on observation, worker and management interviews, after the latest BFC visit, the factory installed belt covers on 4 washing machines (3 from the previous assessment and 1 more that management thought it should be fixed) which had no belt covers. This process was completed on September 8, 2015. Management, worker interviews and our observation also confirmed that the maintenance was made regularly.